



— Druckverlustkurve ohne nachgeschalteten Widerstand.

bar	1	2	3	4	5	6
— l/min	19.6	27.8	34.0	39.3	43.9	48.1